




DOT Inspection			
Date	Friday August 14	Current Time	11:02:32
TimeZone	UTC-07:00	Start Time	12:00 AM
Driver Name	Henry Zhou	Driver ID	henryDri
Co-Driver		Co-Driver ID	
Unidentified Driver Records	false	Exempt Driver Status	false
License #	28291928	License State	AB
VIN	5J6RE3H42BL012793	Trailer ID	TRA-188
Motor Carrier	DTI	Shipping ID	
ELD ID	0A0B	ELD Provider	Diesel Tech Industries

The driver needs to show the DOT Inspection page to authorized safety officials during a roadside inspection.

The DOT Inspection displays records for the current 24-hour period and the previous 14 consecutive days as described in section 4.8.1.3 (a) in Functional Specifications for all ELDs.

 To switch to unidentified driver profile.

 To email a pdf of file for the drivers records.



DOT Inspection											
Duty Status Changes, Intermediate Logs and (PC/YM)											
Time	Event	Status	Origin	Location	Lat.	Long.	Distance	Hours	Odometer	Eng Hours	Comment
07:00:00	On Duty - Not Driving	1	Driver	4mi WNW Edmonton AB	53.57	-113.57	0	0.0	0	0.0	Load
08:30:00	Driving	1	Automatic	4mi WNW Edmonton AB	53.57	-113.57	0	0.0	0	0.0	
14:00:00	Off Duty	1	Driver	4mi WNW Edmonton AB	53.57	-113.57	0	0.0	0	0.0	Break
15:00:00	Driving	1	Automatic	4mi WNW Edmonton AB	53.57	-113.57	0	0.0	0	0.0	
19:00:00	On Duty - Not Driving	1	Driver	4mi WNW Edmonton AB	53.57	-113.57	0	0.0	0	0.0	Unload

Engine Power Up and Shut Down							
Time	Event	Location	Lat.	Long.	Odometer	Eng Hours	Seq. No.
06:55:00	Engine On - Precise Location	4mi WNW Edmonton AB	53.57	-113.57	0	0.0	28
13:59:00	Engine Off - Precise Location	4mi WNW Edmonton AB	53.57	-113.57	0	0.0	31
14:55:00	Engine On - Precise Location	4mi WNW Edmonton AB	53.57	-113.57	0	0.0	33
19:10:00	Engine Off - Precise Location	4mi WNW Edmonton AB	53.57	-113.57	0	0.0	36

Note: The DOT Inspection example above meets the requirements of FMCSA, the DOT Inspection that meets the requirements of Canadian roadside inspection is not ready, which will be available in the next version of DTI's ELD. Password must be entered in order to back out of inspection report.

